



## Feature:

- Inverter technology, heavy duty
- Easy to operate and high efficiency
- Smooth cutting surface
- Automatic overload and temperature protection.
- Be able to cut stainless steel and all kinds of metal

### How to choose one CUT plasma cutting machine?

Thickness of Steel (mm)	Gas Flow (L/min)	Welding Current	Cutting Speed (m/min)
6mm	3.5	30A	0.24
10mm	4	40A	0.3
20mm	5	100A	0.3
30mm	6	125A	0.3